

Department of Energy

Washington, DC 20585

October 23, 2012

Mr. Michael Storck Division of Environmental Response and Remediation State of Utah Department of Environmental Quality P.O. Box 144840 Salt Lake City, UT 84114-4840

Ms. Vera Moritz U.S. Environmental Protection Agency Region 8, EPR-F 1595 Wynkoop St. Denver, CO 80202-1129

Subject: Errata for Results of 2012 Biomonitoring and Ecological Studies at the Monticello Mill Tailings Site, Utah

Dear Mr. Storck and Ms. Moritz:

Please correct the following typographical error in *Results of 2012 Biomonitoring and Ecological Studies at the Monticello Mill Tailings Site, Utah:*

In Table 2 on page 5 of the report, the arithmetic mean for Segment 4 was reported as 2.18 mg/kg Se. The correct value is 0.90 mg/kg Se.

This error did not affect other calculations in the report, and it did not affect the overall conclusion.

Please call me at 970-248-6016 if you have any questions. Please send any correspondence to:

U.S. Department of Energy Office of Legacy Management 2597 Legacy Way Grand Junction, CO 81503

Sincerely,



cc:

T. Bartlett, Stoller

L. Sheader, Stoller

File: MNT 030.02(A) rc grand junction

\Monticello\10-16-12 EPA UDEQ Biomonitoring Results Errata Letter.doc

