

**DR. MODESTO IRIARTE TECHNOLOGICAL
MUSEUM (FORMER BONUS FACILITY)**

2012 ANNUAL RADIOLOGICAL SURVEY REPORT

**RINCON
PUERTO RICO**

**DRAFT
January 2013**



FOR THE PUERTO RICO ELECTRIC POWER AUTHORITY

This page intentionally left blank.

DRAFT
DR. MODESTO IRIARTE TECHNOLOGICAL MUSEUM
2012 ANNUAL RADIOLOGICAL SURVEY REPORT

RINCON, PUERTO RICO

January 2013

Prepared for:

Puerto Rico Electric Power Authority

Prepared by:

URS Corporation
As Prime Contractor

And

MMG, LLC
As Subcontractor

This page intentionally left blank.

Contents

1.0 INTRODUCTION.....	1-1
2.0 PURPOSE	2-1
3.0 LOCATION.....	3-1
4.0 PHYSICAL CONDITION	4-1
5.0 DIRECT RADIATION MONITORING.....	5-1
6.0 CONTAMINATION LEVEL MONITORING.....	6-1
7.0 LABORATORY DATA.....	7-1
8.0 SUMMARY OF RECOMMENDATIONS.....	8-1

List of Tables

Table 1	Survey Locations and Results	3-1
Table 2	Summary of Direct Radiation Monitoring Results	5-1
Table 3	Summary of Direct Radiation Monitoring Quality Control.....	5-2
Table 4	Summary of Contamination Level Monitoring Quality Control	6-4

List of Appendices

Appendix A	Photos
Appendix B	Annual Survey Contamination Survey Forms and Sketches
Appendix C	Physical Condition – Inspection Checklist
Appendix D	Calibration Sheets
Appendix E	Asbestos Monitoring Data

Acronyms and Abbreviations

CFR	Code of Federal Regulations
DOE	U.S. Department of Energy
Dome	BONUS Enclosed Domed Building
dpm/100cm ²	disintegrations per minute per 100 centimeters squared
Dup	Duplicate
MDA	Minimum Detectable Activity
MMG	MMG, LLC
NA	Not Applicable
QA	quality assurance
QC	quality control
RCM	Radiological Control Manager
rem	roentgen equivalent in man
RPD	Relative Percent Difference
RWP	Radiological Work Permit
SAP	Sampling and Analysis Plan
SOP	Standard Operating Procedure
μR/hour	micro-Roentgen per hour

1.0 INTRODUCTION

MMG, LLC (MMG) conducted the comprehensive annual survey at the Dr. Modesto Iriarte Technological Museum (former BONUS Facility) during the dates of 29 – 31 October 2012 with support from PREPA personnel. This survey was conducted in accordance with the Sampling and Analysis Plan (SAP) for the BONUS Facility prepared by the U.S. Department of Energy (DOE) (or DOE contractor) as amended by a 16 January 2001 Memorandum from Webb to Alvarado. The survey was also altered, as presented below in this report, in consideration of the covering of contamination areas/surfaces by paint and/or concrete, the shielding (concrete floor) placed on the Basement Level, the verification survey performed in January 2005 (refer to 22 February 2005 Memorandum entitled: *2004 Annual Survey and Verification Survey for Basement Floor*), and subsequent annual surveys. This report is organized in accordance with Section 6.2 of the SAP. The sampling and inspection results are discussed below.

This page intentionally left blank.

2.0 PURPOSE

The purpose of this effort was to conduct an annual radiological survey - to ensure that exposure to employees, the public and the environment to levels of ionizing radiation are as low as reasonably achievable and demonstrate that levels of radioactivity at the facility remain within the criteria that support the basis for continued use as a museum.

This page intentionally left blank.

3.0 LOCATION

This sampling and inspection effort focused on the BONUS Enclosed Domed Building (Dome). Surveys and inspections were performed on the (1) exterior of the entombment (concrete monolith where the entombed reactor vessel resides), (2) Main Level, and (3) Basement Level. Table 1 provides a list of specific survey locations.

Table 1. Survey Locations and Results

Sampling Location	Sample Number	Dose Rate (μR/hour)	Total Contamination (dpm/100 cm ²)	Removable Contamination (dpm/100 cm ²)	Comments
Routine Sampling					
Pipe Chase Face	1	5	<MDA	<MDA	Monolith Top
Pipe Chase Face	2	4	<MDA	<MDA	Monolith Top
Pipe Chase Face	3	5	<MDA	<MDA	Monolith Top
Pipe Chase Face	4	4	<MDA	<MDA	Monolith Top
Top Plug Face #1	5	5	<MDA	<MDA	Monolith Top
Top Plug Face #1	6	5	<MDA	<MDA	Monolith Top
Top Plug Face #1	7	5	<MDA	<MDA	Monolith Top
Top Plug Face #2	8	5	<MDA	<MDA	Monolith Top
Top Plug Face #2	9	7	<MDA	<MDA	Monolith Top
Top Plug Face #2	10	4	<MDA	<MDA	Monolith Top
Top Plug Face #3	11	5	<MDA Dup=<MDA	<MDA	Monolith Top
Top Plug Face #3	12	5 Dup=5	<MDA	<MDA	Monolith Top
Top Plug Face #3	13	4	<MDA	<MDA	Monolith Top
Top Plug Face #4	14	5	<MDA	<MDA	Monolith Top
Top Plug Face #4	15	4	<MDA	<MDA	Monolith Top
Top Plug Face #4	16	5	<MDA	<MDA	Monolith Top
Top Plug Top Surface	17	4	<MDA	<MDA	Monolith Top
Top Plug Top Surface	18	4	<MDA	<MDA Dup=<MDA	Monolith Top
Top Plug Top Surface	19	4	875	<MDA	Monolith Top
Main Floor Water Column	20	4	<MDA	<MDA	Main Level-Controlled Area
Main Floor Water Column	21	3	<MDA	<MDA	Main Level-Controlled Area
Instrument Thimble #1	22	5	<MDA Dup=<MDA	<MDA	Main Level-Controlled Area
Instrument Thimble #2	23	5	<MDA	<MDA	Main Level-Controlled Area
Instrument Thimble #3	24	5	<MDA	<MDA	Main Level-Controlled Area
Pipe Chase Ext Hatch	25	5	<MDA	<MDA	Main Level-Controlled Area
Instrument Thimble #4	26	5	<MDA	<MDA	Main Level-Controlled Area
Fuel Pool Purif. Floor, area	27	16	16,550	<MDA	Main Level-Controlled Area
Fuel Pool Purif. Floor, area	27A	4	<MDA	<MDA	Main Level-Controlled Area. Taken to define elevated area associated with 27 and 28.
Fuel Pool Purif Floor, area	27B	4	<MDA	<MDA	Main Level-Controlled Area. Taken to define elevated area associated with 27 and 28.
Fuel Pool Purif. Floor (CM005)	28	14	71,828 Dup=76,622	<MDA Dup=<MDA	Main Level-Controlled Area

Table 1 (Continued)

Sampling Location	Sample Number	Dose Rate ($\mu\text{R}/\text{hour}$)	Total Contamination ($\text{dpm}/100\text{ cm}^2$)	Removable Contamination ($\text{dpm}/100\text{ cm}^2$)	Comments
Routine Sampling (continued)					
Side of Liq. Waste Ret. Tank #1	30	18	1,001	<MDA	Basement Level, Att. A – Fig.s 4 and 6
Side of Liq. Waste Ret. Tank #2	31	15 Dup=15	1,668	<MDA	Basement Level, Att. A – Fig.s 4, 5, and 6
F.W. Heater Room (Wall)	40A	12 Dup=12	6,086 Dup=6,587	<MDA Dup=<MDA	Basement Level, Att. A – Fig. 9
F.W. Heater Room (Wall)	40B	10	<MDA	<MDA	Basement Level, Att. A – Fig. 9
Vapor Sphere Room	42	4	<MDA	<MDA	Basement Level
Vapor Sphere Room	43	3	<MDA	<MDA	Basement Level
Condenser Room Entry Wall (Block)	50A	5	<MDA	<MDA	Basement Level, Att. A – Fig. 11
Condenser Room Entry Wall (Concrete)	50B	5	<MDA	<MDA	Basement Level, Att. A – Fig. 11
Additional Sampling Locations					
Main Floor-Zone 1	65	5	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 2	66	5 Dup=5	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 3	67	5	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 4	68	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 5	69	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 6	72	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 7	73	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 8	74	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 9	75	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 9 Smear	9A	NA	NA	<MDA	Main Level-Public Access
Main Floor-Zone 9 Smear	9B	NA	NA	<MDA	Main Level-Public Access
Main Floor-Zone 9 Smear	9C	NA	NA	<MDA	Main Level-Public Access
Main Floor-Zone 10	76	4 Dup=4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 11	77	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear

Table 1 (Continued)

Sampling Location	Sample Number	Dose Rate ($\mu\text{R}/\text{hour}$)	Total Contamination (dpm/100 cm ²)	Removable Contamination (dpm/100 cm ²)	Comments
Additional Sampling Locations (Continued)					
Main Floor-Zone 12	78	4	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 14	79	5	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Main Floor-Zone 13	80	5	NA	<1000dpm/100cm ²	Main Level-Public Access. Masslin Smear
Basement Floor-Zone 1	70	6	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 2	71	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 3	81	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 4	89	6	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 5	90	4	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 6	91	7	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 7	92	4	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 8	93	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 9	94	4	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 10	95	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 11	96	4	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 12	97	3	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 13	98	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 14	99	4 Dup=4	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 15	100	3	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 16	101	4	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 17	102	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear
Basement Floor-Zone 18	103	5	NA	<1000dpm/100cm ²	Basement Level Masslin Smear

Table 1 (Continued)

Sampling Location	Sample Number	Dose Rate ($\mu\text{R}/\text{hour}$)	Total Contamination ($\text{dpm}/100 \text{ cm}^2$)	Removable Contamination ($\text{dpm}/100 \text{ cm}^2$)	Comments
Additional Sampling Locations (Continued)					
Basement Floor-Condenser Room Debris	CR-1	5	<MDA	<MDA	Basement Level
Basement Floor-Debris	D-1	5 Dup=5	<MDA	<MDA	Basement Level

$\text{dpm}/100 \text{ cm}^2$ = disintegrations per minute per 100 centimeters squared

Dup = Duplicate

MDA = Minimum Detectable Activity

NA = Not Applicable

$\mu\text{R}/\text{hour}$ = micro-Roentgen per hour

4.0 PHYSICAL CONDITION

Appendix C provides a copy of the facility inspection checklist used during the annual survey. Findings and observations are provided below.

- **Site Surveillance Features:** Asphalt of the access road and parking area is in fair and usable condition (Appendix A, Figures 34, 35, and 37). The motor of the entrance gate was not operational at the time of the survey, but was manually operated by the attending guard (Appendix A, Figure 35). The security guard controlled access into the gated facility and kept log of visitors. The Dome monolith plaques were in fair condition. The fence surrounding the property is functional at controlling access, however, there are several places where the barbed wire is missing (Figures 36 through 38). No immediate action is necessary.
- **Dome-Entombed Concrete Monolith and Monolith Penetrations:** Inspection of the Concrete Monolith (Appendix A, Figures 5 and 6) area revealed superficial cracks throughout the surface of the structure (Appendix A, Figure 1). Superficial cracks are also present along the base of the “top plug” of the concrete monolith top (Appendix A, Figures 2 and 3). All dose rate measurements taken around the structure were not significantly different from background measurements taken. No immediate action is necessary. Oil/grease was observed on the top of the Concrete Monolith due to dripping from the crane system above (Appendix A, Figure 4). It is recommended that drip pans/pads be placed at those locations where oil/grease is accumulating on the Concrete Monolith.
- **Dome-External Piping Systems:** Inspection of accessible external piping systems revealed no significant indications of deterioration. Some areas of flaking paint were noted. No immediate action is necessary.
- **Dome-Basement Level:** Corrosion is evident on all metal surfaces within approximately 6 in. of the floor, including contaminated surfaces. However, the concrete floor cover (installed in late 2004) covers all floor areas and bases of metallic structures/equipment where surface contamination was present, which is preventing contact with previously accessible contaminated and corroding surfaces. Only surface fissures/cracks were noted in the concrete floor covering (Appendix A, Figure 17). Control measures (fixed with paint and concrete layer in some places), which were previously implemented, were inspected and do not require maintenance at this time. Ongoing and routine assessment of accessible surfaces in the basement is recommended to evaluate the continued effectiveness of the concrete cover flooring and control measures (e.g., paint) emplaced on previous contamination areas. Access to areas with historical removable contamination is being effectively controlled (Appendix A, Figures 19 and 21). No immediate action is necessary.

Residue, which has built up within the large chamber in the Condenser Room, was observed on the floor of the Condenser Room (Appendix A, Figure 25). The residue clings to the interior surface of the chamber until its weight causes it to fall off and some has exited the chamber through its open doors (Appendix A, Figure 24). Radiological survey was performed on the loose material and it was determined to have no discernible elevated radiation or radioactive contamination levels (see below). No immediate action is necessary.

- **Dome-Basement Level Flooding:** Inspection of this level revealed no standing water on the floors. Storm water drains appear to be functioning properly, but silt/mud remains in the sump (Appendix A, Figure 20). PREPA personnel indicate that water does accumulate in the sump, but evaporates leaving silt/mud behind. Sampling and removal of silt/mud should be planned within the next two to three years (repeat from 2011), which would increase the capacity of the sump to retain water until it evaporates.

In 2011 it was reported that rainwater infiltration was occurring in two places: 1) due to tears/holes in the rubber gasket around the exterior base of the Dome and 2) deterioration of the metal frame of the Basement Level loading door. PREPA implemented corrective action on these two issues by installing a new gasket around the exterior base of the Dome (Appendix A, Figures 30 and 31) and by sealing the metal frame of the Basement Level loading door with expanding foam sealer (Appendix A, Figures 32 and 33). The corrective actions appear to be effective as no signs of recent or active infiltration were observed (Appendix A, Figures 22 and 26).

- **Dome-Main Level:** The Main Level (Controlled Area) is that portion of the Main Level that is not accessible to the public (Appendix A, Figure 4). The two historical contamination sites remain covered with floor tiles; the tile work is in good condition and is effective in reducing the dose levels. One area adjacent to the north side of the Monolith is also covered with lead bricks (Appendix A, Figure 13), which is effective in reducing elevated dose rate levels in this area. Ongoing and routine assessment of the floor tile and lead bricks in this area is recommended. There is also no discernable evidence of work and/or damage affecting the control measures (floor tiles) on the Main Level, Museum Area (Appendix A, Figures 7 through 12). The safety guard along the railing, which protects from falls to the Basement Level below, is in good condition (Appendix A, Figure 16) and access control signs are properly placed along the railing. However, the gate within the railing system, which provides access from the Museum Area to the Controlled Area, has no lock (Appendix A, Figure 14). It is recommended that a pad lock be placed where appropriate on the Main Level rail system access door.
- **Dome-Mezzanine Level:** Access to ladders and stairways leading to the mezzanine level are being effectively maintained and controlled (Appendix A, Figure 16). The structure appears sound and in good condition. No immediate action is necessary.
- **Dome-Exterior:** Inspection of the Dome structure (Appendix A, Figure 28) did not reveal any significant structural discrepancies, although the paint on the Dome shell has faded and is flaking in spots. The metallic pass-through portal at the northern entrance still shows signs of significant corrosion (Appendix A, Figure 29) and flaking paint. The southern entrance portal is in good condition (Appendix A, Figure 15) as it is within the museum entrance and protected from the elements. It is recommended that corrosion control coating and new paint be applied to the north entrance pass-through portal to prevent any structural or mechanical damage to the entrance door mechanism. PREPA has awarded a contract to paint the Dome-Exterior for execution in 2013.
- **Surrounding Land:** Inspection the surrounding land within approximately 0.25 miles of the site revealed no significant changing features or activities that might affect site security. The beach immediately adjacent to the site continues to be a popular surfing location. The adjacent lighthouse and surrounding scenic overlook continues to be a

popular place for the local population and vacationers to watch the sun set. No immediate action is necessary.

- **General Site Upkeep:** The buildings and grounds appear well maintained and the grass had been recently mowed (Appendix A, Figures 34 and 35). No immediate action is necessary.
- **Site Security:** A security guard was present at all times during the survey. No immediate action is necessary.
- **Erosion:** Inspection of the surrounding property and slopes to the beach revealed no significant changes or signs of excessive erosion. Dense vegetation on the slopes from the facility to the beach appears to be effectively controlling erosion (Appendix A, Figure 38). No immediate action is necessary.

This page intentionally left blank.

5.0 DIRECT RADIATION MONITORING

The Table 1 presents direct radiation monitoring results for this survey. Appendix B provides survey records and sketches depicting survey locations for the direct radiation monitoring conducted during this annual comprehensive survey. Direct radiation measurements were taken with a Ludlum Micro-R Meter, Model 19, at 30 cm from the source or survey location. Table 2 summarizes these results.

Table 2. Summary of Direct Radiation Monitoring Results

Location	Dose Rate at 30 cm from Source ($\mu\text{R}/\text{hour}$)			Expected Exposure Rate ^a		Annual Dose Limits (rem/year)	
	Min. ($\mu\text{R}/\text{hour}$)	Ave. ($\mu\text{R}/\text{hour}$)	Max. ($\mu\text{R}/\text{hour}$)	Max. Exposure (hour/year)	Rate (rem/year)	Rad Worker	Visitor
Monolith Top	4	4.7	7	416	0.003	2	NA
Main Level (Controlled Area)	3	6.4	16	416	0.007	2	NA
Main Level (Public Access)	4	4.4	5	2,080 (employee)	0.010	2	NA
				832 (visitor)			
Basement Level	3	5.9	18	416	0.007	2	NA

rem = roentgen equivalent in man

^aBased conservatively on the maximum-recorded dose rate at a conservative exposure scenario. For example, exposure level for the Monolith top would be $7 \mu\text{R}/\text{hour} \times (1 \text{ rem}/1,000,000 \mu\text{R}) \times (8 \text{ hours}/1 \text{ week}) \times (52 \text{ weeks}/1 \text{ year}) = 0.003 \text{ rem}/\text{year}$.

The results summarized in the Table 2 indicate that there are no Radiation Areas in the BONUS Facility as defined in Title 10 Part 835 of the Code of Federal Regulations (10 CFR 835), which is 0.005 rem/hour at 30 cm or 5,000 $\mu\text{R}/\text{hour}$ at 30 cm for the dose rate measurements conducted at BONUS). The highest dose rates recorded at 30 cm in the BONUS Facility are well below the limit defining a radiation area. The radiation levels exhibited throughout the facility do not approach annual dose limits for radiological workers or site visitors based on conservative exposure scenarios summarized in the table above.

Instrument calibrations and daily response check records (pre-survey and post-survey each day of use) are maintained at the BONUS facility. Appendix D provides a copy of instrument calibration sheets. Duplicate field measurements were also made at a rate of 5% of the routine measurements and are summarized in Table 3. All quality assurance (QA)/quality control (QC) checks performed within acceptable limits.

Table 3. Summary of Direct Radiation Monitoring Quality Control

Location	Result ($\mu\text{R}/\text{hour}$)		RPD (%)	Comments
	Initial	Duplicate		
12	5	5	0	Very good
31	15	15	0	Very good
40A	12	12	0	Very good
66	5	5	0	Very good
76	4	4	0	Very good
99	4	4	0	Very good
D-1	5	5	0	Very good

RPD = Relative Percent Difference = $[(\text{Sample} - \text{Duplicate})/((\text{Sample} + \text{Duplicate})/2)] \times 100$

6.0 CONTAMINATION LEVEL MONITORING

Table 1 presents contamination level monitoring results for this survey. Appendix B provides contamination survey records and sketches depicting survey locations for the surface contamination measurements conducted during this annual comprehensive survey. Measurements were taken with a Ludlum 44-9 probe coupled to a Ludlum 2221 Scaler/Ratemeter. Total surface and removable contamination surveys were conducted in accordance with Standard Operating Procedures (SOPs) PBR-11.3.1 and 11.4.1. Contamination level results are summarized below.

Concrete Monolith

There are no radioactive Contamination Areas (as defined in 10 CFR 835) associated with the exterior of the Concrete Monolith structure. Smear samples were collected from the surface of the Concrete Monolith to assess transferable or removable surface beta/gamma contamination. None of the smear samples exhibited removable contamination above the MDA. One survey locations exhibited total surface contamination levels above the MDA (location 19 at 875 dpm/100 cm²). This value is well below the survey action level for total surface beta/gamma contamination (5,000 dpm/100 cm²). It is recommended that the Concrete Monolith Top be designated as a Controlled Area due to the presence of slightly elevated fixed surface beta/gamma contamination levels. Marking/posting of this area is not required; however, administrative procedures should be in place to ensure that no intrusive (disturbing the Concrete Monolith surface) work is performed on this level without review and approval by the Radiological Control Manager (RCM). Job-specific Radiological Work Permits (RWPs) may be required for any future intrusive work on the Concrete Monolith Top.

Main Level (Controlled Area)

There are no radioactive Contamination Areas associated with the controlled area (inside the railing and Plexiglas) of the Main Level. Smear samples were collected from the floor surface of the Main Level (controlled area) to assess transferable or removable surface beta/gamma contamination. None of the smear samples exhibited removable contamination above MDA. However, two planned survey locations, 27 and 28, had total surface beta/gamma contamination levels above the 5,000 dpm/100 cm² action level (16,550 and 71,828 dpm/100 cm², respectively). It is recommended that the Main Level (controlled area) remain designated as a Controlled Area due to the presence of elevated fixed surface beta/gamma contamination and be marked/posted in accordance with Section 6.7 of SOP PBR-11.1.4 (modify posting to avoid alarming visitors – current posting is acceptable). Administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface) work is performed in this area without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area.

Main Level (Public Access Area)

The Main Level (public access area) was evaluated for transferable/removable surface contamination only (i.e., only smear samples were performed). These results and previous surveys indicate that there are no radioactive Contamination Areas associated with the public

access area (outside the railing and Plexiglas) of the Main Level. Masslin samples (survey locations 65-69 and 72-80) were collected from the floor surface of the Main Level (public access area) to assess transferable or removable surface beta/gamma contamination. Masslin smear samples exhibited no removable contamination above MDA or 1,000 dpm/100 cm², except location 75 showed slightly elevated levels on the masslin sample (representing Zone 9, approximately 500 ft² area). Zone was further evaluated by collected on three discrete smear samples from the floor (Appendix B, survey sketch). All three smears exhibited no removable contamination above MDA or 1,000 dpm/100 cm². Historically, fixed surface contamination does exist on the concrete floor of the Main Level (public access area), but has been shielded by the placement of tiles in this area (Appendix A, Figure 10). Despite the fact that fixed contamination has been shielded with floor tiles, it is recommended that this area remain a Controlled Area. Marking/posting of this area is not required; however, administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area. It is recommended that at least three distinct smear samples be collected from Zone 9 (location 75) prior to masslin sampling during the 2013 annual survey.

Basement Level

Since the Basement Level floor has been covered with approximately 4-in of concrete, all floor sampling locations on this level were evaluated for transferable/removable surface contamination only (i.e., only smear samples/masslin were performed). Masslin samples (survey locations 70, 71, 81, and 89-103) were collected from the floor surface of the Basement Level to assess transferable or removable surface beta/gamma contamination. Masslin smear samples exhibited no removable contamination above MDA or 1,000 dpm/100 cm². In addition to the masslin samples performed on the floor throughout the level, total and removable contamination was assessed on other surfaces (other than floor) that have been covered with paint and/or concrete due to historical removable contamination (survey locations 30, 31, 40A, 40B, 50A, and 50B). None of the smear samples from these locations exhibited removable contamination above MDA. However, one of these survey locations, 40A (Appendix A, Figure 9), had total surface beta/gamma contamination levels above the 5,000 dpm/100 cm² action level (6,086 dpm/100 cm²). Two additional survey locations, 30 and 31, exhibited a total surface contamination level above MDA, but well below the 5,000 dpm/100 cm² action level. Based on these results, there are no radioactive Contamination Areas associated with the Basement Level.

Two additional survey locations (42 and 43) were evaluated in the Vapor Sphere Room where a tank was historically used for radioactive waste/material storage (a sign indicating radioactive material storage was also present on the door). These survey locations were taken from on top of the newer concrete floor. Both removable and total surface readings at these two locations were below MDA.

In addition to the planned survey locations, PREPA personnel pointed out two locations where debris had accumulated:

- Residue, which has built up within the large chamber in the Condenser Room, was observed on the floor of the Condenser Room as mentioned above (Appendix A, Figure

- 25). The “chunks” of residue were scanned/frisked resulting in no discernible elevated levels of radioactivity. A confirmatory discrete sampling location (location CR-1) was evaluated both removable and total surface contamination and found to be below MDA.
- During the re-sealing of the metal framing of the Basement Level loading door, old sealing was removed and accumulated inside on the Basement Level floor (Appendix A, Figure 23). The debris items were scanned/frisked resulting in no discernible elevated levels of radioactivity. A confirmatory discrete sampling location (location D-1) was evaluated for both removable and total surface contamination and found to be below MDA.

Recommendations for access control and posting of this area are provided below:

- Proposed public access area in Basement Level – Despite the fact that fixed contamination has been shielded with the added concrete flooring in the basement, it is recommended that the proposed public access area in the Basement Level remain designated as a controlled area. Marking/posting of this area is not required; however, administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area.
- Proposed non-public access area in the Basement Level – Despite the fact that elevated removable surface contamination levels have been fixed through control measures, it is recommended that the proposed non-public access areas in the Basement Level remain designated as a controlled area and be marked/posted in accordance with Section 6.7 of SOP PBR-11.1.4 (modify posting to avoid alarming visitors). The non-public access areas are those portions of the Liquid Waste Pump Room/F.W. Heater Room and Retention Tank Room that will be partitioned off as “no public access”. Those portions of these rooms that will allow public access will be controlled as stated in the previous bullet. Administrative procedures should be in place to ensure that no intrusive (disturbing the floor or wall surfaces) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area.

Contamination Survey QA/QC

Instrument calibration records and daily response check records (pre- and post-survey daily checks) are maintained at the BONUS facility. Appendix D provides a copy of instrument calibration records. Duplicate field measurements were also made at a rate of 5% and are summarized in Table 4.

Table 4. Summary of Contamination Level Monitoring Quality Control

Location	Result (dpm/100 cm ²)		RPD (%)	Comments
	Initial	Duplicate		
11 (Total Surface)	<MDA	<MDA	NA	Good
18 (Removable)	<MDA	<MDA	NA	Good
22 (Total Surface)	<MDA	<MDA	NA	Good
28 (Total Surface & Removable)	71,828	76,622	6%	Good
	<MDA	<MDA	NA	Good
40A (Total Surface & Removable)	6,086	6,587	8%	Good
	<MDA	<MDA	NA	Good

$$RPD = [(Sample - Duplicate) / ((Sample + Duplicate) / 2)] \times 100$$

Contamination survey QA/QC checks are acceptable.

7.0 LABORATORY DATA

There were no radiological laboratory data generated to support this survey. However, Appendix E includes asbestos monitoring data collected within the facility in 2012. There are no additional recommendations for the facility radiological monitoring and protection associated with the 2012 asbestos monitoring results.

This page intentionally left blank.

8.0 SUMMARY OF RECOMMENDATIONS

Based on previous surveys and the 2012 Annual Survey results presented above, the following recommendations are provided:

- No “general” RWPs are required for non-intrusive, routine activities (surveys, tours, etc.) at the Facility. Activities that may disturb floors, walls, and/or other potentially contaminated surfaces should be written in a brief planning document and submitted to the RCM for review. As noted in the bullets below, job-specific RWPs may be required for any future intrusive work in the facility.
- Physical Condition:
 - Oil/grease is dripping from the crane system onto the Concrete Monolith top (Appendix A, Figure 4). It is recommended that drip pans/pads be placed at those locations where oil/grease is accumulating on the Concrete Monolith.
 - Storm water drains appear to be functioning properly in the Basement Level, but the sump is filling with silt/mud (Appendix A, Figure 20). Sampling and removal of silt/mud should be planned within the next two to three years (repeat from 2011).
 - The metallic pass-through portal at the northern entrance shows signs of significant corrosion (Appendix A, Figure 29) and flaking paint. It is recommended that corrosion control coating and new paint be applied to the north entrance pass-through portal to prevent any structural or mechanical damage to the entrance door mechanism (repeat from 2011).
 - The gate within the railing system, which provides access from the Museum Area to the Controlled Area, has no lock (Appendix A, Figure 14). It is recommended that a pad lock be placed where appropriate on the Main Level rail system access door.
- Concrete Monolith: It is recommended that the Concrete Monolith Top remain designated as a controlled area due to the presence of elevated fixed surface beta/gamma contamination levels. Marking/posting of this area is not required; however, administrative procedures should be in place to ensure that no intrusive (disturbing the Concrete Monolith surface) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work on the Concrete Monolith Top.
- Main Level (non-public access area): It is recommended that the Main Level (controlled area) remain designated as a controlled area due to the presence of elevated fixed surface beta/gamma contamination and exposure rates and be marked/posted in accordance with Section 6.7 of SOP PBR-11.1.4 (modify posting to avoid alarming visitors – current posting is acceptable). Administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area.
- Main Level (public access area): Despite the fact that fixed contamination has been shielded with floor tiles, it is recommended that the Main Level (public access area) remain a controlled area. Marking/posting of this area is not required; however,

administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area. Due to a masslin sample with with slightly elevated readings, it is also recommended that at least three distinct smear samples be collected from Zone 9 (location 75) prior to masslin sampling during the 2013 annual survey.

- Proposed public access area in Basement Level: Despite the fact that fixed contamination has been shielded with the added concrete flooring in the basement, it is recommended that the proposed public access area in the Basement Level remain designated as a controlled area. Marking/posting of this area is not required; however, administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area.
- Proposed non-public access area in the Basement Level – Despite the fact that elevated removable surface contamination levels have been fixed through control measures, it is recommended that the non-public access areas in the Basement Level remain designated as a controlled area and be marked/posted in accordance with Section 6.7 of SOP PBR-11.1.4 (modify posting to avoid alarming visitors). The non-public access areas are those portions of the Liquid Waste Pump Room/F.W. Heater Room and Retention Tank Room that will be partitioned off as “no public access”. Those portions of these rooms that will allow public access will be controlled as stated in the previous bullet. Administrative procedures should be in place to ensure that no intrusive (disturbing the floor surface or control measures) work is performed on this level without review and approval by the RCM. Job-specific RWPs may be required for any future intrusive work in this area.
- Per SOP PBR-11.1.4, routine surveys are required to ensure removable contamination remains below action levels. For this purpose, it is recommended that the annual comprehensive survey and quarterly surveys continue to be repeated. Quarterly surveys should focus on public access areas in close proximity to historical removable contamination areas (F.W. Heater Room/Liquid Waste Pump Room and Retention Tank Room).

This page intentionally left blank.

APPENDIX A
PHOTOS

This page intentionally left blank.



Figure 1. Entombment Top (North Side) – Surface Cracks (Typical)




Figure 2. Entombment Top (Top Plug)



Figure 3. Entombment Top (Top Plug) – Surface Cracks (Typical)




Figure 4. Entombment Top (Top Plug) – Oil Drip/Stains from Overhead Crane



Figure 5. Entombment (Northeast Side)



Figure 6. Entombment (North Side)



Figure 7. Main Level (North Side) – Overhead View



Figure 8. Main Level (Northeast Side) – Overhead View



Figure 9. Main Level (East Side) – Overhead View



Figure 10. Main Level (Southeast Side) – Overhead View



Figure 11. Main Level (South Side) – Overhead View



Figure 12. Main Level (Controlled Area) – Tiles Over Fixed Surface Contamination



Figure 13. Main Level (Controlled Area) – Shielding with Concrete and Lead Bricks



Figure 14. Main Level (Controlled Area) – Gate Access to Controlled Area



Figure 15. Main Level (Museum Area) – South Entrance



Figure 16. Main Level (Museum Area) – Ladder to Mezzanine Locked-Out




Figure 16. Main Level (Museum Area) – Guard Over Opening to Basement Level



Figure 17. Basement Level – Cracks in Concrete Floor (Typical)




Figure 18. Basement Level – Sample Location 50A (Small Crack in Concrete Shielding)



Figure 19. Basement Level – Concrete Filled Sink



Figure 20. Basement Level – Lowest Point in Basement with No Standing Water



Figure 21. Basement Level – New Asbestos Containing Material Sign in Room Where Sampling Locations 40A and 40B are Located



Figure 22. Basement Level – Loading Access Door (No Signs of Leak through Door)



Figure 23. Basement Level – Loading Access Door (Debris from Old Seal Material)



Figure 24. Basement Level – Condenser Room (North Side Access)



Figure 25. Basement Level – Condenser Room (Debris from Condenser on Floor)



Figures 26A and 26B. Basement Level – Beneath North Entrance (No Signs of Recent Water Leak into Basement Level)



Figure 27. Dome Structure – Interior with Fire Suppression Piping



Figures 28A and 28B. Dome Structure – Exterior



Figure 29. Dome Structure – North Entrance (Exterior with Significant Corrosion)



Figures 30A and 30B. Dome Structure – Flexible Gasket/Seal



Figure 31. Dome Structure – Flexible Gasket/Seal (Retains Water in Some Locations)



Figure 32. Exterior Structure – Basement Loading Access Door



Figures 33A, 33B, and 33C. – Basement Loading Access Door (New Expanding Foam Seal to Prevent Rain Water from Entering the Basement Level)



Figure 34. Ancillary Buildings



Figure 35. Grounds, Guard Shack and Entrance Gate



Figure 36. Fence – North Side



Figure 37. Fence – South Side



Figures 38A, 38B, and 38C. Fence – West (Beach) Side



Figure 39. Ancillary Building – Previous Water Tank Overflow has been Shut-Off (No Standing Water)



Figure 40. Personnel Performing Instrument Response Checks

APPENDIX B
ANNUAL SURVEY CONTAMINATION SURVEY FORMS AND SKETCHES

This page intentionally left blank.

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 29 Oct 2012 0920hr Task Number NA

Specific Area of Survey: Entombed Building-North Side $MDA = ((2.71/Tbkg + 3.3\sqrt{Bkg/Tbkg + Bkg/Ts})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey $A = (Sample - Bkg)/E \times CF$

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	47	812
<u>NA</u>						%			

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		$\beta\gamma$ Removable	$\beta\gamma$ Total	$\beta\gamma$ Removable	$\beta\gamma$ Total
1	North Side	see	46	see	<MDA
2	North Side	Smear	46	Smear	<MDA
3	North Side	Data	53	Data	<MDA
4	North Side	}	56	}	<MDA
24	North Side		39		<MDA
26	North Side		49		<MDA
<u>NA</u>					

Survey Technician: A. Luca

Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP
(former BONUS REACTOR FACILITY) Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE:

Entombed Reactor Building

Time: 0925 hrs

Date: Yr 12 Mo 10 Dy 29

Task: Comprehensive Survey

RWP: NA

Map key: ° = Sample Location □ = Air Sampler Location _ = Core Sample

Dose Rate Abbreviations: CT/WB/GA, where CT = Contract, WB = Whole Body, GA = General Area


Building: Entombed Reactor Building

Location: North Side

Sketch:

Entombment System - North View

1 = Sample Locations



Instruments (Model and Serial Numbers): Model 19 # 148190

Survey Technician(s): A. Luca + C. Webb

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/29/12 0940hrs Task Number NA

Specific Area of Survey: Entombed Building-NoruthWest Side MDA= $((2.71/Tbkg + 3.3\sqrt{Bkg/Tbkg+Bkg/Ts})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	47	812
<u>NA</u>						%			

SURVEY DATA		Survey Map Attached <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No				
No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²		
		By Removable	By Total	By Removable	By Total	
5	Top Plug Face	see	54	see	<MDA	
6	Top Plug Face	Smear	46	Smear	<MDA	
7	Top Plug Face	Data	42	Data	<MDA	
8	Top Plug Face		65		<MDA	
9	Top Plug Face		60		<MDA	
10	Top Plug Face		60		<MDA	
11	Top Plug Face		55		<MDA	
12	Top Plug Face		55		<MDA	
13	Top Plug Face		49		<MDA	
14	Top Plug Face		53		<MDA	
15	Top Plug Face		64		<MDA	
16	Top Plug Face		51		<MDA	
17	Top Plug - Top Surface		50		<MDA	
18	Top Plug - Top Surface		48		<MDA	
19	Top Plug - Top Surface		68		875	
11dup	duplicate		NA	58	NA	<MDA

Survey Technician: A. Luca
 Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)
Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE: Entombed Reactor Building Time: 0955 hrs Date: Yr 12 Mo 10 Dy 29

Task: Comprehensive Survey RWP: NA


Map key: ° = Sample Location □ = Air Sampler Location _ = Core Sample

Dose Rate Abbreviations: CT/WB/GA, where CT = Contract, WB = Whole Body, GA = General Area

Building: Entombed Reactor Building Location: Entombment System – Top (Plan View)

Sketch:

1 = Sample Locations



12 dwp
= 5

Instruments (Model and Serial Numbers): Model 19 #148190

1.9 µR/hr

Survey Technician(s): A. Lea + C. Webb

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/30/12 0910 hrs Task Number NA

Specific Area of Survey: Entombed Building-South Side $MDA = ((2.71/Tbkg + 3.3\sqrt{Bkg/Tbkg + Bkg/Ts})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey $A = (Sample - Bkg)/E \times CF$

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	65	950
NA	-----	-----	-----	-----	-----	----- %	-----	-----	-----

SURVEY DATA		Survey Map Attached <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		$\beta\gamma$ Removable	$\beta\gamma$ Total	$\beta\gamma$ Removable	$\beta\gamma$ Total
22	South Side	see smear data	39	see smear data	<MDA
22dup	duplicate	NA	37	NA	<MDA
NA	-----	-----	-----	-----	-----

Survey Technician: A. Lucca
 Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP
(former BONUS REACTOR FACILITY) Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE: Entombed Reactor Building Time: 1500hrs Date: Yr 12 Mo 10 Dy 29

Task: Comprehensive Survey RWP: NA

Map key: ° = Sample Location □ = Air Sampler Location _ = Core Sample


Dose Rate Abbreviations: CT/WB/GA, where CT = Contract, WB = Whole Body, GA = General Area

Building: Entombed Reactor Building Location: South Side

Sketch:

Entombment System - South View

1 = Sample Locations



Instruments (Model and Serial Numbers): Model 19 # 148190

Survey Technician(s): I. Figueroa + C Webb

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/30/12 0915 hrs Task Number NA

Specific Area of Survey: Entombed Building-SouthWest Side $MDA = ((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg + Bkg/Ts)})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey $A = (Sample - Bkg)/E \times CF$

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	65	950
NA									

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
23	SouthWest Side	see Smear Data	35	see Smear Data	2MDA
NA					
NA					

Survey Technician: A. Lucca

Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)
Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE: Entombed Reactor Building Time: 1505 hrs Date: Yr 12 Mo 10 Dy 29

Task: Comprehensive Survey RWP: NA


Map key: ° = Sample Location □ = Air Sampler Location _ = Core Sample

Dose Rate Abbreviations: CT/WB/GA, where CT = Contract, WB = Whole Body, GA = General Area

Building: Entombed Reactor Building Location: SouthWest Side

Sketch: **Entombment System - Southwest View**

1 = Sample Locations



Instruments (Model and Serial Numbers): Model 19 # 148190

Survey Technician(s): I. Figueroa + C. Webb

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/30/12 0950 Task Number NA

Specific Area of Survey: Entombed Building-NoruthWest Side $MDA = ((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg + Bkg/Ts)})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey $A = (Sample - Bkg)/E \times CF$

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	65	950
<u>NA</u>						%			

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
25	NorthWest Side	See Smear Data	37	See Smear Data	< MDA
<u>NA</u>					
<u>NA</u>					

Survey Technician: A. Lucca

Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)
Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE: Entombed Reactor Building Time: 1510 hrs Date: Yr 12 Mo 10 Dy 29

Task: Comprehensive Survey RWP: NA


Map key: ° = Sample Location □ = Air Sampler Location _ = Core Sample

Dose Rate Abbreviations: CT/WB/GA, where CT = Contract, WB = Whole Body, GA = General Area

Building: Entombed Reactor Building Location: NorthWest Side

Sketch: Entombment System - Northwest View

1 = Sample Locations



Instruments (Model and Serial Numbers): Model 19 #148190

Survey Technician(s): F. Fisneroa + C. Webb

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/30/12 0840hrs Task Number NA

Specific Area of Survey: Entombed Building-Main Floor MDA= $((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. Type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	65	950
<u>NA</u>						%			

SURVEY DATA		Survey Map Attached <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		$\beta\gamma$ Removable	$\beta\gamma$ Total	$\beta\gamma$ Removable	$\beta\gamma$ Total
20	Main Floor	<u>NA</u>	<u>56</u>	<u>NA</u>	<u><MDA</u>
21	Main Floor	<u>see Smear</u>	<u>67</u>	<u>see Smear</u>	<u><MDA</u>
27	Main Floor	<u>Data</u>	<u>462</u>	<u>Data</u>	<u>16,550</u>
28	Main Floor		<u>1,788</u>		<u>71,828</u>
27A	Main Floor		<u>67</u>		<u><MDA</u>
27B	Main Floor		<u>59</u>		<u><MDA</u>
28 Dup	Main Floor		<u>1,903</u>		<u>76,622</u>
<u>NA</u>					

Survey Technician: A. Lucca
 Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/29/12 1510 hrs Task Number NA

Specific Area of Survey: Entombed Building-Main Floor MDA= $((2.71/Tbkg + 3.3\sqrt{Bkg/Tbkg+Bkg/Ts}))/E \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. Type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	52	158
<i>NA</i>									

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
65	Main Floor-Masslin (Zone 1)	41	NA	< MDA	NA
66	Main Floor-Masslin (Zone 2)	31	}	< MDD	}
67	Main Floor-Masslin (Zone 3)	55		< MDD	
68	Main Floor-Masslin (Zone 4)	41		< MDD	
69	Main Floor-Masslin (Zone 5)	35		< MDD	
72	Main Floor-Masslin (Zone 6)	35		< MDD	
73	Main Floor-Masslin (Zone 7)	47		< MDA	
74	Main Floor-Masslin (Zone 8)	37		< MDA	
75	Main Floor-Masslin (Zone 9)	77*		< MDD	
76	Main Floor-Masslin (Zone 10)	58		< MDD	
77	Main Floor-Masslin (Zone 11)	48		< MDD	
78	Main Floor-Masslin (Zone 12)	52		< MDA	
79	Main Floor-Masslin (Zone 14)	50		< MDA	
80	Main Floor-Masslin (Zone 13)	38		< MDA	

Survey Technician: J. Reyes
Reviewed By: C. Webb

*MDA < 200 dpm/100cm² (cannot be quantified due to large area survey).

*This cpm activity is equivalent to the MDA established for smears at 100cm² area. Since the area where the masslin wipe was taken (zone 9) is approximately 500ft², the activity on the masslin in dpm/100cm² is expected to be well below MDA. However, smear samples will be taken from this zone for confirmation.

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)
Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE: Entombed Reactor Building Time: 1440 Date: Yr 12 Mo 10 Dy 29

Task: Comprehensive Survey RWP: NA


Map key: ° = Sample Location □ = Air Sampler Location _ = Core Sample

Dose Rate Abbreviations: CT/WB/GA, where CT = Contract, WB = Whole Body, GA = General Area

Building: Entombed Reactor Building Location: Main Floor

Sketch:

No.	μR/hr
Zone 1= 65	5
Zone 2= 66	5
Zone 3= 67	5
Zone 4= 68	4
Zone 5= 69	4
Zone 6= 72	4
Zone 7= 73	4
Zone 8= 74	4
Zone 9= 75	4
Zone 10= 76	4
Zone 11= 77	4
Zone 12= 78	4
Zone 13= 80	5
Zone 14= 79	5
Zone 2=	5 dup
Zone 10=	4 dup
20	4
21	3
27	16
28	14
27A	4
27B	4



Instruments (Model and Serial Numbers): Model 19 #148190

Survey Technician(s): J. Reyes + C. Webb

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/30/12 1315 hrs Task Number NA

Specific Area of Survey: Entombed Building-Basement Floor MDA= $((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. Type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	43	771
<u>NA</u>						%			

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²			
		By Removable	By Total	By Removable	By Total		
30	Basement Floor-Side of Tank #1	See Smear Data	67	See Smear Data	1,001		
31	Basement Floor-Side of Tank #2		83		1,668		
40A	Basement Floor-Wall (4" from floor)		189		6,086		
40B	Basement Floor-Wall (4" from floor)		51		<MDA		
42	Basement Floor		42		<MDA		
43	Basement Floor		43		<MDA		
50A	Basement Floor-Wall (block)		44		<MDA		
50B	Basement Floor-Wall (concrete)		36		<MDA		
40A Dup	Basement Floor-Wall (4" from floor)		NA		201	NA	6,587
NA							
NA							
NA							
NA							
NA							
NA							
NA							
NA							

Survey Technician: F. Figueroa
 Reviewed By: C. Webb

*MDA is total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/31/12 1115 hrs Task Number NA

Specific Area of Survey: Entombed Building-Basement Floor MDA= $((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. Type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA*
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	49	155
						%			

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²		
		By Removable	By Total	By Removable	By Total	
70	Masslin - Zone 1	34	H/A	<MDA	H/A	
71	Masslin - Zone 2	66	}	<MDA	}	
81	Masslin - Zone 3	55		<MDA		
89	Masslin - Zone 4	49		<MDA		
90	Masslin - Zone 5	49		<MDA		
91	Masslin - Zone 6	51		<MDA		
92	Masslin - Zone 7	47		<MDA		
93	Masslin - Zone 8	42		<MDA		
94	Masslin - Zone 9	43		<MDA		
95	Masslin - Zone 10	38 ^{gross}		10/31/12		<MDA
96	Masslin - Zone 11	41		<MDA		
97	Masslin - Zone 12	40		<MDA		
98	Masslin - Zone 13	41		<MDA		

Survey Technician: A. Lopez + I. Figueroa

Reviewed By: C. Webb

*MDA < 200 dpm/100 cm² (cannot be quantified due to large area survey).

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/31/12 11:35 hrs Task Number NA

Specific Area of Survey: Entombed Building-Basement Floor MDA= $((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E) \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. Type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading (cpm)	MDA [*] dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	49	155
		1 1			1 1	%	1		

SURVEY DATA		Survey Map Attached <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			
No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		βγ Removable	βγ Total	βγ Removable	βγ Total
99	Masslin - Zone 14	44	N/A	2MDA	N/A
100	Masslin - Zone 15	39	}	1MDA	}
101	Masslin - Zone 16	42		1MDA	
102	Masslin - Zone 17	47		1MDA	
103	Masslin - Zone 18	40		1MDA	
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					

Survey Technician: A. Lucca + I. Figueroa
 Reviewed By: C. Webb

*MDA < 200 dpm/100 cm² (cannot be quantified due to large area survey).

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/31/12 0915hrs Task Number NA

Specific Area of Survey: Basement Level MDA= $(2.71/Tbkg + 3.3\sqrt{Bkg/Tbkg+Bkg/Ts})/E \times CF$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E \times CF$

Inst. Type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	512	44	786
<i>smear canter</i> Ludlum 2221	11	3/23/13	"	"	3/23/13	16 %	1011	49	155

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
CR-1	Rust Piece	43	39	<MDA	<MDA
D-1	Old door insulation foam	NA	37	NA	<MDA
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					

Survey Technician: A. Lunca

Reviewed By: C. Webb

*MDA is removable/total in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)
Rincón, Puerto Rico

RADIOLOGICAL SURVEY REPORT (MAP)

SITE: Entombed Reactor Building Time: 14:45 Date: Yr 12 Mo 10 Dy 30 *cw 10/30/12*

Task: Comprehensive Survey RWP: NA


Building: Entombed Reactor Building Location: Basement Floor

Sketch:

cw 10/30/12
cw 10/30/12

No.	μ R/hr
Zone 1 = 70	6
Zone 2 = 80	5
Zone 3 = 81	5
Zone 4 = 89	6
Zone 5 = 90	4
Zone 6 = 91	4
Zone 7 = 92	4
Zone 8 = 93	5
Zone 9 = 94	4
Zone 10 = 95	5
Zone 11 = 96	4
Zone 12 = 97	3
Zone 13 = 98	5
Zone 14 = 99	4
Zone 15 = 100	5
Zone 16 = 101	4
Zone 17 = 102	5
Zone 18 = 103	5
30	10
31	15
40A	12
40A Dup	12
40B	10
42	4
43	3
50A	5
50B	5
Zone 14 dup	4
31 dup	15
CR-1	5
D-1	5
D-1	5 dup

70 @ 10/30/12



= SCM Survey Above 100 cm² limit

Instruments (Model and Serial Numbers): Model 19 #148190

Survey Technician(s): A. Lucca + J. Reyes

Notes:

Entombment Top

$$MDA = \left(\frac{2.71}{5} + 3.3 \sqrt{\frac{47}{5} + \frac{47}{2}} \right) \cdot 6.67 = 812 \text{ dpm}/100 \text{ cm}^2$$

$$MDA_{\text{cpm}} = \left(\frac{MDA}{6.67} \cdot .16 \right) + Bck_{\text{cpm}} = \left(\frac{812}{6.67} \cdot .16 \right) + 47 = 66 \text{ cpm}$$

Smear Count Station - Main Level Entrance

$$*MDA = \left(\frac{2.71}{10} + 3.3 \sqrt{\frac{52}{10} + \frac{52}{1}} \right) \cdot 1 = 158 \text{ dpm}/100 \text{ cm}^2$$

$$*MDA_{\text{cpm}} = (158) \cdot (.16) + 52 = 77 \text{ cpm}$$

*This is also location for scanning Maslin, smear samples.

Date: 10/29/12

Prepared By: C. Webb

Reviewed By: D. Jenkins

Notes:

Main Level - Restricted Access Area

$$MDA = \left(\frac{2.71}{5} + 3.3 \sqrt{\frac{65}{5} + \frac{65}{2}} \right) \cdot 6.67 = 950 \text{ dpm}/100 \text{ cm}^2$$

$$MDA_{\text{cpm}} = \left(\frac{950}{6.67} \cdot .16 \right) + 65 = 88 \text{ cpm}$$

Smear Station - Counting at Main Level Entrance

$$MDA = \left(\frac{2.71}{10} + 3.3 \sqrt{\frac{48}{10} + \frac{48}{1}} \right) \cdot 1 = 152 \text{ dpm}/100 \text{ cm}^2$$

$$MDA_{\text{cpm}} = (152) \cdot (.16) + 48 = 72 \text{ cpm}$$

Basement Level Background Area

$$MDA = \left(\frac{2.71}{5} + 3.3 \sqrt{\frac{43}{5} + \frac{43}{2}} \right) \cdot 6.67 = 771 \frac{\text{dpm}}{100 \text{ cm}^2}$$

$$MDA_{\text{cpm}} = \left[\left(\frac{771}{6.67} \right) \cdot .16 \right] + 43 = 61 \text{ cpm}$$

After performing measurements at locations 40A and 40B, personnel frisked hands and feet. No readings discernable above background.

Date: 10/30/12Prepared By: e. webbReviewed By: D. Jenkins

Notes:

Basement Level Background Area

$$MDA = \left(\frac{\frac{2.71}{5} + 3.3 \sqrt{\frac{44}{5} + \frac{44}{2}}}{.16} \right) \cdot 6.67 = 786 \text{ dpm}/100\text{cm}^2$$

$$MDA_{\text{cpm}} = \left(\frac{786}{6.67} \right) \cdot .16 + 44 = 63 \text{ cpm}$$

Smear + Mass/In Count Station - Main Level Entrance

$$MDA = \left(\frac{\frac{2.71}{5} + 3.3 \sqrt{\frac{49}{10} + \frac{49}{1}}}{.16} \right) \cdot 1 = 155 \text{ dpm}/100\text{cm}^2$$

$$MDA_{\text{cpm}} = (155) \cdot .16 + 49 = 74 \text{ cpm}$$


Surveyed (scan/frisk) loose material on floor of Condenser Room on Basement Level. No readings discernable above background. One static B/8 total measurement recorded (CR-1) on largest piece of material + one removable B/8 smear collected (~400 cm² area) from this piece. All readings below MDA. This material is releasable.

Surveyed (scan/frisk) foam material removed from Basement Level cargo door. No readings discernable above background. One static B/8 total measurement recorded (D-1). All readings below MDA. This material is releasable.

Date: 10/31/12

Prepared By: C. WebbReviewed By: P. Jenkins

Notes: Performed general survey of the Condenser Room on Basement Level. Spot-checks on condenser performed with Ludlum 2221 + 44-9 probe. Internal + external surfaces were scanned. No readings discernable above background. This was not a 100% or Comprehensive survey.



Date: 10/31/12

Prepared By: C. Webb

Reviewed By: D. Jenkins

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/29/12 1405 Task Number NA

Specific Area of Survey: Smears MDA= $((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E$

Purpose of Survey: Year 2012 Comprehensive Survey A= $(Sample-Bkg)/E$

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading	MDA dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	52	158
<u>NA</u>									

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		βy Removable	βy Total	βy Removable	βy Total
<u>1</u>	<u>Smear</u>	<u>42</u>	<u>NA</u>	<u><MDA</u>	<u>NA</u>
<u>2</u>	<u>"</u>	<u>45</u>	}	<u><MDA</u>	}
<u>3</u>	<u>"</u>	<u>43</u>		<u><MDA</u>	
<u>4</u>	<u>"</u>	<u>50</u>		<u><MDA</u>	
<u>5</u>	<u>"</u>	<u>53</u>		<u><MDA</u>	
<u>6</u>	<u>"</u>	<u>42</u>		<u><MDA</u>	
<u>7</u>	<u>"</u>	<u>43</u>		<u><MDA</u>	
<u>8</u>	<u>"</u>	<u>54</u>		<u><MDA</u>	
<u>9</u>	<u>"</u>	<u>49</u>		<u><MDA</u>	
<u>10</u>	<u>"</u>	<u>37</u>		<u><MDA</u>	
<u>11</u>	<u>"</u>	<u>35</u>		<u><MDA</u>	
<u>12</u>	<u>"</u>	<u>41</u>		<u><MDA</u>	
<u>13</u>	<u>"</u>	<u>58</u>		<u><MDA</u>	
<u>14</u>	<u>"</u>	<u>46</u>		<u><MDA</u>	
<u>15</u>	<u>"</u>	<u>45</u>		<u><MDA</u>	
<u>16</u>	<u>"</u>	<u>44</u>		<u><MDA</u>	

Survey Technician: A. Luca

Reviewed By: C. Webb

*MDA is removable in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/29/12 1930 Task Number NA

Specific Area of Survey: Smears MDA= $(2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E$

Purpose of Survey: Year 2012 Comprehensive Survey A=(Sample-Bkg)/E

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading	MDA* dpm/100 cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	52	158
<u>NA</u>						%			

SURVEY DATA

Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
17	<u>Smears</u> "	47	NA	MDA	
18a	"	46	}	MDA	<u>MDA</u> CW 10/29/12
18b	duplicate 1/ count	53		MDA	<u>MDA</u> CW 10/29/12
19	"	43		MDA	<u>MDA</u> CW 10/29/12
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					

Survey Technician: A. L. Sosa
 Reviewed By: C. Webb

*MDA is removable in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time ³⁰ 10/29/12 10:30 Task Number N/A
 Specific Area of Survey: Smears ^{cw 10/30/12} MDA= $((2.71/Tbkg + 3.3\sqrt{Bkg/Tbkg+Bkg/Ts}))/E$
 Purpose of Survey: Year 2012 Comprehensive Survey A=(Sample-Bkg)/E

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading	MDA dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	48	152
						%			^{cw 10/30/12}

SURVEY DATA		Survey Map Attached <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			
No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
9A	SMEAR	47	N/A	< MDA	N/A
9B	"	33		< MDA	
9C	"	32		< MDA	
20	"	43		< MDA	
21	"	42		< MDA	
22	"	37		< MDA	
23	"	45		< MDA	
24	"	48		< MDA	
25	"	41		< MDA	
26	"	52		< MDA	
27	"	44		< MDA	
27A	"	38		< MDA	
27b	"	40		< MDA	
28a	"	42		< MDA	
28b	Duplicate count.	56		< MDA	
30	Smear	52		< MDA	
31	"	48		< MDA	

Survey Technician: A. Lucca
 Reviewed By: C. Webb

cw 10/29/12

*MDA is removable in dpm/100 cm²

TECHNOLOGICAL MUSEUM DR. MODESTO IRIARTE BEAUCHAMP (former BONUS REACTOR FACILITY)

Rincón, Puerto Rico

CONTAMINATION SURVEY FORM

Project: BONUS - MMG Date/Time 10/30/12 1305 hrs Task Number NA

Specific Area of Survey: Smears MDA= $((2.71/Tbkg + 3.3\sqrt{(Bkg/Tbkg+Bkg/Ts)})/E$

Purpose of Survey: Year 2012 Comprehensive Survey A=(Sample-Bkg)/E

Inst. type	Serial #	Cal. due date	Probe type	Serial #	Cal. due date	Efficiency	Ct. Time Tbkg/Ts (minutes)	Bkgd Reading	MDA* dpm/100cm ²
Ludlum 2221	149991	3/23/13	44-9	154535	3/23/13	16 %	1011	48	152
		1 1			1 1	%	1		col 10/30/12

SURVEY DATA Survey Map Attached Yes No

No.	Description/Location	Gross Counts in CPM		Contamination in dpm/100 cm ²	
		By Removable	By Total	By Removable	By Total
40A	SMears	41	NA	<MDA	NA
40A Dup	"	39		<MDA	
40B	"	29		<MDA	
42	"	31		<MDA	
43	"	57		<MDA	
50A	"	48		<MDA	
50B	"	50		<MDA	
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					
NA					

Survey Technician: A. Lucca
 Reviewed By: C. Webb

*MDA is removable in dpm/100 cm²

Page 1 of 2
 CW 10/30/12 CW 10/30/12

APPENDIX C
PHYSICAL CONDITION – INSPECTION CHECKLIST

This page intentionally left blank.

Inspection Checklist

BONUS Decommissioned Facility, Rincón, Puerto Rico

Date of This Inspection/Revision:

29-31 October 2012

Last Inspection:

4 August 2011

Inspectors:

A. Luca

and

C. Webb

Next Inspection (Planned):

Summer 2013

No.	Item	Issue	Action/Notes
1	Specific site surveillance features	See attached table.	Inspect. <i>see page 3/3.</i>
2	Dome—entombed concrete monolith and monolith penetrations	Structural defects or degradation can result in loss of containment of radioactive materials.	Inspect for possible indications of structural problems, such as cracking, staining, and spalling. Notes: <i>No change - minor superficial cracks.</i>
3	Dome—external piping systems	Systems were flushed during decommissioning. Incidental contamination remains, which may be released if systems corrode or otherwise fail.	Inspect for possible indications of deterioration, such as peeling and blistering paint, staining, and flaking. Notes: <i>No noticeable change. No signs of leak or discharge.</i>
4	Dome—Basement Level	Some areas contain radiological contamination in excess of DOE standards; the general public is not allowed access to contaminated areas.	Note condition of access control barricades. Notes: <i>Good condition - new asbestos sign on door of Ancillary Water Pump Room.</i>
5	Dome—Basement Level flooding	Water accumulating in Basement Level may mobilize and redistribute surface contamination.	Inspect for gasket and storm water drains. Notes: <i>Gasket has been replaced - no water accumulation. Some water accumulating on gasket.</i>
6	Dome—Main Level	Some areas contain radiological contamination in excess of DOE standards; the general public is not allowed access to contaminated areas.	Note condition of access control barricades, ceramic floor tile, and lead blocks; note general housekeeping. Notes: <i>No change - controls in good condition.</i>
7	Dome—Mezzanine Level	Some areas contain radiological contamination in excess of DOE standards; the general public is not allowed access to contaminated areas.	Note condition of access control to mezzanine; note general housekeeping. Notes: <i>Gate to mezzanine stairs was locked. Access to ladder - behind locked gate.</i>
8	Dome—exterior	Building should appear well maintained	Visually inspect. Notes: <i>Paint faded (color), but dome surface protected.</i>

9	Surrounding land	New or changing features or activities adjacent to the site may affect site security.	Note changes within 0.25 mile (400 m) of site. Notes: <i>No apparent changes, Lighthouse park has been repaired/updated & is open.</i>
10	General site upkeep	Building should appear well maintained.	Observe and evaluate changes in site conditions. Notes: <i>Good - grass needs to be mowed. Grass was mowed during survey. Good.</i>
11	Site security	Security guard should be stationed at site at all times.	Ensure security guard is present. Notes: <i>Guard was present.</i>
12	Erosion	Ensure that hill slopes and beach adjacent to site are not actively eroding in a way that could adversely affect the Facility.	Evaluate erosional features on adjacent slopes and beach. Notes: <i>No noticeable erosion on beach.</i>

mowed

**Checklist Of Site Specific Surveillance Features
BONUS Decommissioned Facility, Rincón, Puerto Rico**

Feature	Comment
Access road and parking area	Asphalt - No Change. some broken asphalt, but functional.
Entrance gate	Motor-operated - motor is not operational, but guard was present and maintained key+lock for gate.
Access through security gate	Note security of site; sign-in required on log sheet Guard required sign-in on log sheet + recorded pertinent information.
Security fence	Chain-link, topped with three strands of barbed wire Fence has some damage, but no holes/gaps. Barbed wire is down in some sections.
Dome—monolith plaques	Visually inspect - monolith structural integrity has not changed + plaques are in good condition. - in English + Spanish.

APPENDIX D
CALIBRATION SHEETS

This page intentionally left blank.



Designer and Manufacturer
of
Scientific and Industrial
Instruments

CERTIFICATE OF CALIBRATION

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A.

CUSTOMER PUERTO RICO ELECTRIC PWR AUTH ORDER NO. 20196202/375034

Mfg. Ludlum Measurements, Inc. Model 2221 Serial No. 149991

Mfg. Ludlum Measurements, Inc. Model 44-9 Serial No. PR/54535

Cal. Date 23-Mar-12 Cal Due Date 23-Mar-13 Cal. Interval 1 Year Meterface 202-159

Check mark applies to applicable instr. and/or detector IAW mfg. spec. T. 74 °F RH 30 % Alt 759.8 mm Hg

New Instrument Instrument Received Within Toler. +-10% 10-20% Out of Tol. Requiring Repair Other-See comments

Mechanical ck. Meter Zeroed Background Subtract Input Sens. Linearity

F/S Resp. ck Reset ck. Window Operation Geotropism

Audio ck. Alarm Setting ck. Batt. ck. (Min. Volt) 4.4 VDC

Calibrated in accordance with LMI SOP 14.8 rev 12/05/89. Calibrated in accordance with LMI SOP 14.9 rev 02/07/97.

Instrument Volt Set 900 V Input Sens. 50 mV Det. Oper. 900 V at 50 mV Threshold Dial Ratio 100 = 10 mV

HV Readout (2 points) Ref./Inst. 500 / 502 V Ref./Inst. 2000 / 2011 V

COMMENTS:

sr90Y90:sn:5281,ACT:99,198dpm,EFF:24.09% 4pi
 ct:23,954cpm,bg:56,sct:23,898cpm
 sl37:sn:0745,act:172,018dpm, EFF:0.16% 4pi(gamma)
 ct:342cpm,bg:56cpm,sct:286cpm
 sl37:sn:158-112,ACT:6,156dpm EFF:20.79% 4pi(Beta)
 ct:1,336cpm,bg:56cpm,sct:1,280cpm
 o60:sn:0886:ACT:7,891dpm, EFF:14.68% 4pi(Beta)
 ct:1,215cpm,bg:56cpm,sct:1,159cpm
 i63:sn:0909,ACT:243,756dpm EFF:0.10% 4pi
 ct:322cpm,bg:56cpm,sct:266cpm
 gamma Calibration: GM detectors positioned perpendicular to source except for M 44-9 in which the front of probe faces source.

All efficiencies taken at 1/4" from surface of detector.
 Cs137:sn:2008 reads≈3,085cpm 1/4" from surface.
 Sr90Y90:sn:342-09 reads≈13,908cpm 1/4" from surfacs.
 Firmware:261010

RANGE/MULTIPLIER	REFERENCE CAL. POINT	INSTRUMENT REC'D "AS FOUND READING"	INSTRUMENT METER READING*
x1K	400kcpm	400	400
x1K	100kcpm	100	100
x100	40kcpm	400	400
x100	10kcpm	100	100
x10	4kcpm	400	400
x10	1kcpm	100	100
x1	400cpm	400	400
x1	100cpm	100	100

*Uncertainty within ± 10% C.F. within ± 20% ALL Range(s) Calibrated Electronically

REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*	Log Scale	REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*
400kcpm	40011	40011		500kcpm	500K	500K
40kcpm	4001	4001		50kcpm	50K	50K
4kcpm	400	400		5kcpm	5K	5K
400cpm	40	40		500cpm	500	500
40cpm	4	4		50cpm	50	50

Ludlum Measurements, Inc. certifies that the above instrument has been calibrated by standards traceable to the National Institute of Standards and Technology, or to the calibration facilities of International Standards Organization members, or have been derived from accepted values of natural physical constants or have been derived by the ratio type of calibration techniques. calibration system conforms to the requirements of ANSI/NCSL Z540-1-1994 and ANSI N323-1978 State of Texas Calibration License No. LO-1963

Reference Instruments and/or Sources: 73410 1131 781 059 280 60646 70897 Ra-226 S/N Y982 -137 Gamma S/N 1162 G112 M565 5105 T1008 T879 E552 E551 720 734 1616 Neutron Am-241 Be S/N T-304

Alpha S/N Beta S/N Other m 500 S/N 94940 Oscilloscope S/N Multimeter S/N 78401031

Calibrated By: [Signature] Date 23-Mar-12

Reviewed By: [Signature] Date 23-Mar-12

AC Inst. Passed Dielectric (Hi-Pot) and Continuity Test Only Failed:



Designer and Manufacturer
of
Scientific and Industrial
Instruments

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A.

CONVERSION CHART

Customer PUERTO RICO ELECTRIC PWR AUTH Date 23-Mar-12 Order # 20196202/375034

Model 2221 Serial No. 149991 Detector Model 44-9 Serial No. PR154535

Source Cs-137 194.6 mCi Cs-137 20 mCi High Voltage 900 V

Input Sensitivity 50 mV

Reference Point	"As Found" Readings (CPM):		After Adjustment Readings (CPM):	
	Analog	Range/Scale	Analog	Range/Scale
150 mR/hr	360	X1K	360	X1K
50 mR/hr	155	X1K	155	X1K
15 mR/hr	50	X1K	50	X1K
5 mR/hr	180	X100	180	X100
1.5 mR/hr	50	X100	50	X100
1.0 mR/hr	340	X10	340	X10

Reference Point	"As Found" Readings:		After Adjustment Readings:	
	Digital	Count Time	Digital	Count Time
150 mR/hr	36242	6 Sec	36242	6 Sec
50 mR/hr	15210		15210	
15 mR/hr	5266		5266	
5 mR/hr	1805		1805	
1.5 mR/hr	546		546	
1.0 mR/hr	348		348	

Signature: [Handwritten Signature] Date 23-Mar-12



Designer and Manufacturer
of
Scientific and Industrial
Instruments

CERTIFICATE OF CALIBRATION

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A. ³⁷⁵⁰³⁴
ORDER NO. 20196202/275035-50

CUSTOMER PUERTO RICO ELECTRIC PWR AUTH ORDER NO. 20196202/275035-50

Mfg. Ludlum Measurements, Inc. Model 19 Serial No. 148190

Cal. Date 23-Mar-12 Cal Due Date 23-Mar-13 Cal. Interval 1 Year Meterface 202-016

Check mark applies to applicable instr. and/or detector IAW mfg. spec. T. 74 °F RH 30 % Alt 699.8 mm Hg

New Instrument Instrument Received Within Toler. +10% 10-20% Out of Tol. Requiring Repair Other-See comments

Mechanical ck. Meter Zeroed Background Subtract Input Sens. Linearity
 F/S Resp. ck Reset ck. Window Operation Geotropism
 Audio ck. Alarm Setting ck. Batt. ck. (Min. Volt) 2.2 VDC
 Calibrated in accordance with LMI SOP 14.8 rev 12/05/89. Calibrated in accordance with LMI SOP 14.9 rev 02/07/97.

Instrument Volt Set 525 V Input Sens. 32 mV Det. Oper. _____ V at _____ mV Threshold Dial Ratio _____ = _____ mV

HV Readout (2 points) Ref./Inst. _____ / _____ V Ref./Inst. _____ / _____ V

COMMENTS:
sl137~luci checksource sn:2008 reads:~290uR/hr with checksource label placed against the dimple in front of instrument can.

Gamma Calibration: GM detectors positioned perpendicular to source except for M 44-9 in which the front of probe faces source.

RANGE/MULTIPLIER	REFERENCE CAL. POINT	INSTRUMENT REC'D "AS FOUND READING"	INSTRUMENT METER READING*
5000	4000 uR/hr	3950	4000
5000	1000 uR/hr	950	1000
500	400 uR/hr = 76,000 cpm	395	400
500	100 uR/hr	95	100
250	200 uR/hr = 38,000 cpm	210	200
250	100 uR/hr	110	100
50	7600 cpm	40	40
50	1900 cpm	10	10
25	3800 cpm	20	20
25	950 cpm	5	5

*Uncertainty within ± 10% C.F. within ± 20% 50, 25 Range(s) Calibrated Electronically

REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*	Log Scale	REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*
Initial readout						

Ludlum Measurements, Inc. certifies that the above instrument has been calibrated by standards traceable to the National Institute of Standards and Technology, or to the calibration facilities of International Standards Organization members, or have been derived from accepted values of natural physical constants or have been derived by the ratio type of calibration techniques. This calibration system conforms to the requirements of ANSI/NCCL Z540-1-1994 and ANSI N323-1978 State of Texas Calibration License No. LO-1963

Reference Instruments and/or Sources: 73410 1131 781 059 280 60646 70897 Ra-226 S/N Y982
 -137 Gamma S/N 1162 G112 M565 5105 T1008 T879 E552 E551 720 734 1616 Neutron Am-241 Be S/N T-304

Alpha S/N _____ Beta S/N _____ Other _____

m 500 S/N 94940 Oscilloscope S/N _____ Multimeter S/N 78401031

Calibrated By: [Signature] Date 23-Mar-12

Reviewed By: [Signature] Date 23-Mar-12

APPENDIX E
ASBESTOS MONITORING DATA

This page intentionally left blank.



ENVIRONMENTAL HEALTH & SAFETY SERVICES

PMB 142, 400 CALLE CALAF, SAN JUAN, PUERTO RICO, 00918

PHONE NUMBER: 787-855-1901 FAX NUMBER: 787-858-2646

ASBESTOS AIR MONITORING PCM ANALYSIS REPORT

NIOSH 7400 A RULES, ISSUE 2, REVISION 3

Page 1 of 1

Client: A.E.E. Protección Ambiental
Address: Santurce, Puerto Rico
Project: A.E.E. Bonus, Rincón

Sampling Date: 05/16/12
Project No.: RA

SAMPLE ID	AMBIENT SAMPLE LOCATION PERSONAL SAMPLE: NAME, S.S. #	TYPE	FLOW RATE	SAMPLE VOLUME (liters)	AVG. BLANK COUNT	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm ³)	M.F.C. (f/cc)	L.O.D. (f/cc)	R.F.C. (f/cc)	8HR. T.W.A.
FILTER ID	ACTIVITY		(l/min) TIME									
RA 120516 BN01	FIELD BLANK	FB			0.0	100	0.0	0.0				
RA 120516 BN02	FIELD BLANK	FB			0.0	100	0.0	0.0				
RA 120516 BN03	BONUS PLANT MAIN BLDG. GROUND LEVEL, EAST CORNER NEAR ENTRANCE, AREA SAMPLE	BG	10.00 120.0	1200.0	0.0	100	2.5	3.2	0.001	0.002	<0.002	
RA 120516 BN04	BONUS PLANT MAIN BLDG. BASEMENT NORTHWEST CORNER PIPE ROOM, AREA SAMPLE	BG	10.00 120.0	1200.0	0.0	100	6.0	7.6	0.002	0.002	0.002	

Type= BG-Background; EX-Exposure; OS-Outside; PP-Preparation; RM-Removal; CE-Cleaning; CL-Clearance; FB-Field Blank; PR-Personal; EL-Excursion Limit

M.F.C.--Measured Fiber Concentration R.F.C.--Reported Fiber Concentration L.O.D.--Limit of Detection T.W.A.--Time Weighted Average

Microscope #: EHSS 800 Rotometers #: RT-27 HV-141 Num. Samples: 4

Collected By:	Carmen del Pilar Colón EQB#10960243MS	Date:	05/16/12	Analyzed By:	Carmen P. Colón EQB#10960243MS	Date:	05/16/12
Delivery By:	N/A	Date:	N/A	PCM Report Delivery By:	Carmen P. Colón EQB#10960243MS	Date:	05/16/12
Received By:	N/A	Date:	N/A	PCM Report Received By:	Brenda Aponte	Date:	05/16/12
Reviewed By:	Carmen P. Colón EQB#10960243MS	Date:	05/16/12	Comments:			

CARR. #2 KM 39.7 BO. ALGARROBO, VEGA BAJA, PUERTO RICO, 00693