

Contact Records Index for the Rocky Flats Site, Colorado

- CR 2024-01 Solar Ponds Plume Treatment System (SPPTS) utilities reconfiguration project and Interceptor Trench System (ITS) extension tie-in project
- CR 2023-01 Reportable condition for uranium at Point of Evaluation (POE) GS10
- CR-2022-05 Solar Ponds Plume Treatment System (SPPTS) discharge gallery maintenance
- CR-2022-04 Reportable condition for plutonium at Point of Evaluation (POE) SW027
- CR-2022-03 Reportable condition for uranium at Point of Evaluation (POE) GS10
- CR-2022-02 Boron analytical results at Present Landfill groundwater treatment system effluent location PLFSYSEFF
- CR-2022-01 North Walnut Creek Slump (NWCS) exploratory test pits
- CR-2021-05 East Trenches Plume Treatment System (ETPTS) discharge gallery replacement
- CR-2021-04 East Trenches Plume Treatment System (ETPTS) discharge line replacement
- CR-2021-03 Reportable condition for plutonium at Point of Evaluation (POE) SW027
- CR 2021-02 Reportable conditions for uranium at Point of Evaluation (POE) GS10
- CR 2021-01 Rock crossing and drainage channel installation as part of the 2021 Site Roads Maintenance Project
- CR 2020-01 Soil Disturbance Review Plan (SDRP)—Solar Pond Influent (SPIN) vault drain line installation
- CR 2020-02 Mound Site Plume Collection System (MSPCS) transfer line maintenance and Soil Disturbance Review Plan (SDRP)
- CR 2019-04 North Walnut Creek Slump (NWCS) Area and Solar Ponds Plume Treatment System (SPPTS) subsurface investigation and Soil Disturbance Review Plan (SDRP)
- CR 2019-03 North Walnut Creek stormwater diversion and Soil Disturbance Review Plan (SDRP)
- CR 2019-02 Original Landfill (OLF) stabilization project with Soil Disturbance Review Plan (SDRP)
- CR 2019-01 Reportable condition for plutonium 12-month rolling average at Point of Evaluation (POE) SW027
- CR 2018-05 Minor modification of Rocky Flats Legacy Management Agreement (RFLMA) Attachment 2, Legacy Management Requirement

Contact Records Index for the Rocky Flats Site, Colorado

- CR 2018-04 Reportable condition for evaluation purposes for uranium at Walnut Creek Point of Compliance (WALPOC)
- CR 2018-03 Documentation of Rocky Flats Legacy Management Agreement (RFLMA) parties agreement on posting written correspondence and attached guidelines for posting written correspondence
- CR 2018-02 Minor modification to the inspection form attached to the Original Landfill (OLF) Monitoring and Maintenance Plan (M&M Plan)
- CR 2018-01 Original Landfill (OLF) geotechnical investigation work in accordance with attached Soil Disturbance Review Plan (SDRP)
- CR 2017-04 OLF 2017 interim maintenance work: creating positive drainage and minor adjustments to berm heights, in accordance with Soil Disturbance Review Plan (SDRP)
- CR-2017-03 North Walnut Creek Slump (NWCS) 2017 maintenance and Soil Disturbance Review Plan (SDRP)
- CR 2017-02 Reportable condition for evaluation purposes for uranium at Walnut Creek Point of Compliance (WALPOC)
- CR 2017-01 Original Landfill temporary groundwater intercept system
- CR 2016-04 Upgrade of the east subsurface drain located in the east perimeter channel of the Original Landfill, with Soil Disturbance Review Plan (SDRP)
- CR 2016-03 Geoprobe investigation of the groundwater system upgradient of the Original Landfill and the Soil Disturbance Review Plan (SDRP)
- CR 2016-02 Mound Site Plume Treatment System (MSPTS) reconfiguration project soil disturbance review report and explanation of significant differences
- CR 2016-01 Reportable condition for evaluation purposes for uranium at Walnut Creek Point of Compliance (WALPOC)
- CR 2015-10 Area of concern well 10304 reportable condition
- CR 2015-09 Soil Disturbance Review Plan (SDRP) for Solar Ponds Plume Treatment System (SPPTS) interim configuration
- CR 2015-08 Solar Ponds Plume Treatment System interim design and implementation
- CR 2015-07 Vinyl chloride results from the Present Landfill Treatment System (PLFTS) effluent triggered the consultative process
- CR 2015-06 Original Landfill (OLF) implementation of interim action to reestablish surface water management on portions of the OLF, with Soil Disturbance Review Plan (SDRP)
- CR 2015-05 Reportable condition for plutonium 12-month rolling average at Point of Evaluation (POE) SW027

Contact Records Index for the Rocky Flats Site, Colorado

- CR 2015-04 Mound Site Plume Treatment System (MSPTS) reconfiguration conceptual approach
- CR 2015-03 Original Landfill (OLF) immediate response to recent precipitation
- CR 2015-02 Soil Disturbance Review Plan (SDRP) for storage shed photovoltaic upgrades
- CR 2015-01 Reportable condition for uranium 12-month rolling average at Walnut Creek Point of Compliance (WALPOC)
- CR 2014-10 (rescinded) Reportable condition for uranium 12-month rolling average at Walnut Creek Point of Compliance (WALPOC)
- CR 2014-09 Soil Disturbance Review Plan (SDRP) Update for regrading the East Perimeter Channel (EPC) at the Original Landfill (OLF)
- CR 2014-08 Provide flexibility to the flow configuration at the Solar Ponds Plume Treatment System (SPPTS) as part of the ongoing optimization effort
- CR 2014-07 Abandonment of sentinel well 88104 at the Rocky Flats Site, Colorado
- CR 2014-06 Vinyl chloride results from the Present Landfill Treatment System (PLFTS) effluent triggered the consultative process
- CR 2014-05 Reportable condition for evaluation purposes for uranium at Walnut Creek Point of Compliance (WALPOC)
- CR 2014-04 Approval of the installation and operation of an air stripper and the associated Rocky Flats Legacy Management Agreement (RFLMA) Soil Disturbance Review Plan (SDRP) as part of the reconfiguration of the East Trenches Plume Treatment System (ETPTS)
- CR 2014-03 Minor modification to the March 2008 Present Landfill (PLF) Monitoring and Maintenance Plan (M&M Plan)
- CR 2014-02 Minor modification of Rocky Flats Legacy Management Agreement (RFLMA) Attachment 2, Legacy Management Requirements
- CR 2014-01 East Trenches Plume Treatment System (ETPTS) media removal and reconfiguration for air stripper treatment
- CR 2013-03 Soil Disturbance Review Plan (SDRP) for regrading the East Perimeter Channel (EPC) and associated diversion berms at the Original Landfill (OLF)
- CR 2013-02 Reportable Condition at the Original Landfill (OLF)
- CR 2013-01 GS10 flume replacement project and Soil Disturbance Review Plan (SDRP)
- CR 2012-03 Minor Modification of Rocky Flats Legacy Management Agreement (RFLMA) Attachment 1, Site Map, and of RFLMA Attachment 2, Legacy Management Requirements

Contact Records Index for the Rocky Flats Site, Colorado

- CR 2012-02 Improving treatment at the East Trenches Plume Treatment System (ETPTS) by adding an air stripper component
- CR 2012-01 Soil Disturbance Review Plan (SDRP) – Roads maintenance, including grading the road to former A-3 Pond to convert the road to two-track vehicle use
- CR 2011-08 Reportable condition for americium-241 (Am) at Rocky Flats Legacy Management Agreement (RFLMA) Point of Evaluation (POE) GS10
- CR 2011-07 Soil Disturbance Review Plan (SDRP)—Pond A-3 and Present Landfill (PLF) pond dam breach project
- CR 2011-06 Soil Disturbance Review Plan (SDRP)—Roads upgrade project involving reconfiguration of a sharp curve west of functional channel 1
- CR-2011-05 Update for reportable condition for uranium at Point of Evaluation (POE) GS10
- CR 2011-04 Reportable condition for uranium at Point of Evaluation (POE) GS10
- CR 2011-03 Resource Conservation and Recovery Act (RCRA) well monitoring results at Original Landfill (OLF) and Present Landfill (PLF)
- CR 2011-02 Replace sentinel well 3370
- CR 2011-01 Replace Mound Site Plume Treatment System (MSPTS) media and maintain/repair discharge gallery
- CR 2010-07 Monitoring results and water treatment at the Mound Site Plume Treatment System (MSPTS) and the East Trenches Plume Treatment System (ETPTS)
- CR 2010-06 Monitoring results at surface water Point of Evaluation (POE) SW027
- CR 2010-05 Statistically higher concentrations of analytes in groundwater downgradient of the Original Landfill (OLF) and Present Landfill (PLF)
- CR 2010-04 Rocky Flats Legacy Management Agreement (RFLMA) Attachment 2: Modification to Revise Monitoring Points
- CR 2010-03 Non-Rocky Flats Legacy Management Agreement (RFLMA) surface water monitoring project for North and South Walnut Creeks
- CR 2010-02 Approval of excavation greater than 3-feet below grade to breach dams A-3, A-4, B-5, C-2, and the Present Landfill dam
- CR 2010-01 Targeted soil sampling at the Original Landfill (OLF) to evaluate residual contamination levels in relation to the Colorado Department of Public Health and Environment's (CDPHE) August 2008 Policy, End of Post-Closure Care
- CR 2009-05 Installation of snow fencing north of the Original Landfill (OLF) and approval of work after closeout of contact record
- CR 2009-04 Replace East Trenches Plume Treatment System (ETPTS) media and make minor changes to the piping configuration

Contact Records Index for the Rocky Flats Site, Colorado

- CR 2009-03 Soil disturbance for road maintenance and improvement work involving the construction of roadside drainage ditches that will not return excavation to preexisting grade
- CR 2009-02 Excavation by Xcel Energy for valve replacement on 12-inch golden pipeline
- CR 2009-01 Phase II and III upgrades to Solar Ponds Plume Treatment System (SPPTS)
- CR 2008-09 Revision of sampling locations to reflect site reconfiguration
- CR 2008-08 Construction of collection sump for Solar Ponds Plume Treatment System (SPPTS)
- CR 2008-07 Path forward for Original Landfill (OLF) seep 7 drain extension, berm maintenance and repair, perimeter channel slope cut and fill, and modification of the Original Landfill (OLF) Monitoring and Maintenance Plan (M&M Plan)
- CR 2008-06 Management of intercepted groundwater during Solar Ponds Treatment System (SPPTS) repair or maintenance activities
- CR 2008-05 Boron and uranium in groundwater downgradient of the Original Landfill (OLF)
- CR 2008-04 Notification of well replacement and well identification change
- CR 2008-03 Exploratory excavations to greater than 3 feet below grade generally between the former interceptor trench pump house and Solar Ponds Plume Treatment System (SPPTS)
- CR 2008-02 Discussion and approval of excavation greater than 3 feet below grade to breach dams A-1, A-2, B-1, B-2, B-3, and B-4
- CR 2008-01 Completion of additional ecological sampling in accordance with Rocky Flats Legacy Management Agreement (RFLMA) Attachment 2, Table 5
- CR 2007-08 Changes to Present Landfill (PLF) inspection and monitoring frequencies and modification of the PLF Monitoring and Maintenance Plan (M&M Plan)
- CR 2007-07 Replacement of monitoring well 45605 (B991 Slump)
- CR 2007-06 Evaluation of elevated nitrate in groundwater samples from AOC well B206989
- CR 2007-05 Grading the slump area south of FC-4 and former building 991
- CR 2007-04 Discussion and approval of soil disturbance for phase III road improvement work involving the construction of roadside drainage ditches that will not return excavation to preexisting grade
- CR 2007-03 Discussion and approval of excavation greater than 3 feet below grade in FC-1 soil borrow area and placement of soil south of former B371 location to eliminate ponding around well heads for wells 33502, 33604, and 33703

Contact Records Index for the Rocky Flats Site, Colorado

- CR 2007-02 Discussion and approval of exploratory excavations to greater than 3 feet below grade around the former interceptor trench pump house
- CR 2007-01 Notification of adverse biological condition, March 27, 2007, Central Operable Unit (COU) boundary fence wildlife deaths
- CR 2006-03 Disposition February–July 2006 monitoring results for arsenic at the Present Landfill Treatment System (PLFTS)
- CR 2006-02 Disposition December–July 2006 monitoring results for boron at the Present Landfill Treatment System (PLFTS)
- CR 2006-01 Disposition December 2005–May 2006 monitoring results for manganese at the Present Landfill Treatment System (PLFTS)