Westow Fustap

## Department of Energy 776

Washington, DC 20545

PA. 12-1

SEP 0 5 1990

Mr. Thomas A. Dickerson Supervisor of Environmental Affairs Carpenter Technology Corporation Engineering and Construction P. O. Box 14662 Reading, Pennsylvania 19612-4662

Dear Mr. Dickerson:

The Department of Energy (DOE) has completed its review of the preliminary radiological data from the surveys of your facility in Reading, Pennsylvania, completed in July and August 1988. We are pleased to inform you that the survey has verified that the radiological condition of your facility is in compliance with applicable DOE Guidelines and that no remedial action or further investigations are necessary.

I am enclosing a copy of the survey report prepared by our contractor, Oak Ridge National Laboratory. Your site will officially be eliminated from further consideration in the Formerly Utilized Sites Remedial Action Program and information supporting that action will be placed in the DOE Public Reading Room in Room IE-190 of the Forrestal Building, 1000 Independence Avenue, S.W., Washington, D.C.

If you have any questions regarding the survey results or our associated actions, contact me at 301-353-5439.

Sincerely,

W. Alexander Williams, PhD Designation and Certification Manager

Off-Site Branch

Division of Eastern Area Programs
Office of Environmental Restoration

Enclosure

bcc:
Weston
R. Foley, ORNL
W. Cottrell, ORNL

EM-40 (3) EM-42 reader Williams reader

EM-421:AWilliams:353=5439:8/31/90:dickerson.aw

EM-421 Williams 9/4/90

EM-42 Fullmer 945/90

M-42 Hiora 9X5790