

AEC/MED INVOLVEMENT AT SITE

Control

- AEC/MED managed operations
- AEC/MED responsible for accountability
- AEC/MED overviewed operations
- Contractor had total control
- unknown

- Health Physics Protection
 - Little or None
 - AEC/MED responsibility
 - Contractor responsibility

MATERIALS HANDLED:

Type (on basis of records reviewed)

- No Radioactive
 - Natural Radioactive from Feed Materials Production
 - Ore
 - Refined Source Material
 - Residue
 - Natural Radioactive Material from Non-Nuclear Activities
 - Man-Made
 - Other
- Comment Uranium metal heating tests

Quantities (on the basis of records reviewed)

- None
 - Production Quantities
 - Small Amounts
- Comment _____

OTHER PERTINENT FACTS:

- Facility was Licensed
 - During AEC/MED-Related Operations
 - For Similar Activities
 - For Other Activities
- Comment _____

Commercial Production Involving Radioactive Material during AEC/MED Operations

Facility was Decontaminated and Released

Availability of Close Out Records

None

Some

Sufficient

Radioactive Status:

	YES	MAYBE	PROBABLY	NOT
Contaminated Potential for Exposure (accessible)	---	---	NOT	---
	---	---	---	X

QUANTITY OF RECORDS AVAILABLE:

Very Little

Some

Sufficient

PROBABILITY OF FINDING ADDITIONAL RECORDS:

Low

Possible

High

RECOMMENDATIONS:

Eliminate

Consider for Remedial Action

Collect More Data

Comment _____

REFERENCES: _____

SUMMARY

Uranium metal slugs were located in an
accepting test of a furnace system. Little
likelihood of contamination. One time test.